

Report Date 7/14/2012

Company L & L Home Solutions
Address PO Box 9 DSM IA
Thermographer

Customer Dustin
Site Address example st
Contact Person




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2012:01:20 09:58:59	
Image Name	dustin ir 2.jpg	
Emissivity	0.91	
Reflected Temperature	68.0 °F	
Object Distance	6.6 ft	

Description